

WSB-2 Digital Display Desktop Whiteness Instrument



Main technical parameters

Model	station WSB -
Measurement range	0 ~ 199
Whiteness formula	blue light whiteness WB=R457
Light source	LED light source
Lighting conditions	comply with GB/T3978 regulation 45/0
Display	LCD display
Measuring the aperture	Φ 30
Minimum	0.1
Measurement repeatability	0.2
Error of indication	≤ & plusmn; 1
Using the environment temperature (5 °C ~ 35 °C)	Humidity (& le; 85% RH)
Transportation and storage environment	temperature (20 °C to 50 °C); Humidity (& le; 90% RH)
Power supply	ac 220V/50Hz